

USED EQUIPMENT CHECKLIST

CONTACT DETAILS

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE,	Nashville, Tn
PHONE:	615-299-9899	POSTAL CODE/ZIP	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY	U.S.

PUMP SPECIFICATIONS

YEAR:	2015	MAKE:	Schwing	MODEL:	SP4800
SERIAL #:	4800143	ENGINE MAKE:	Caterpillar/C13	RADIO REMOTE:	NO
CYLINDER SIZES:	7 inch	ENGINE HRS:	1872.2	ENGINE HP:	328

COMPLETE EVALUATION

		Excellent	Very Good	Good	Fair
General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Overall Condition - Pump	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Operations – Truck	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
General Condition - Truck	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cab Exterior Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cab Interior Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Tires:	Enter % here.				
Rear Tires:	Enter % here..				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PTO Value:	N/A				
Wear Part Value:	50% remaining				
Material Cylinders:	70% remaining				
Boom System:	N/A				
Agitator:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Hopper Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Paint Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X <input type="checkbox"/>

Boom Certified:	<input type="checkbox"/> YES <input type="checkbox"/> NO					
Date Boom Last Inspected:	N/A					
Expiry Date of last Commercial Vehicle Inspection:	N/A					

INCLUDED WITH UNIT					
Tool Box	<input type="checkbox"/> YES <input type="checkbox"/> NO	Tip Hose	<input type="checkbox"/> YES <input type="checkbox"/> NO	Outrigger Pads	<input type="checkbox"/> YES <input type="checkbox"/> NO
Spare Remote	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Water Hose	<input type="checkbox"/> YES <input type="checkbox"/> NO		

Click here to enter text.

DATE OF EVALUATION:	5/23/2023
COMPLETED BY:	L. Wangen

For questions or assistance, please contact Jason Pitt:

jasonpitt@pumppartners.com | 615-476-7606