

USED EQUIPMENT CHECKLIST

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE:	Nashville, TN
PHONE:	615-476-7606	POSTAL CODE/ZIP:	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY:	US
ASKING PRICE: (INCL. COMMISSIONS)		BOTTOM LINE: (INCL. COMMISSIONS)	

YEAR:	2007	MAKE:	Mack	MODEL:	MR688S
VIN	1M2K197C07M039647	ENGINE MAKE:	AI-427	MILEAGE:	*661,828
TRANSMISSION SPEEDS:	18	ENGINE HRS:	*31,484	ENGINE HP:	425
TRANSMISSION TYPE:	T 318 L			DOES A/C FUNCTION	yes

LIST:	DATE:	COMMENT:
Enter text here.	Enter date here.	Enter text here.
Enter text here.	Enter date here.	Enter text here.
Enter text here.	Enter date here.	Enter text here.
Enter text here.	Enter date here.	Enter text here.

YEAR:	2008	BRAND:	Schwing	MODEL:	S 58 SX
SERIAL #:	5800076	BOOM LENGTH:	61 meter	PUMP KIT:	2525H-6
FOLD STYLE:	<input checked="" type="checkbox"/> ROLL <input type="checkbox"/> Z BOOM	RADIO REMOTE:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	PUMP HOURS:	7673
PROPORTIONAL:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CYLINDER SIZE:	10 in		

LIST:	DATE:	COMMENT:
Enter text here.	Enter date here.	Enter text here.
Enter text here.	Enter date here.	Enter text here.
Enter text here.	Enter date here.	Enter text here.

		Excellent	Very Good	Good	Fair
General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Overall Condition - Pump	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Operations – Truck	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Condition - Truck	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Exterior Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Interior Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Front Tires:	90%				
Rear Tires:	90%				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
PTO Value:	50% wear				
Wear Part Value:	50% wear				
Material Cylinders:	50% wear				
Boom System:	35% wear				
Agitator:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
Hopper Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
Paint Condition:	Check box <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Boom Certified:	X YES <input type="checkbox"/> NO				
Date Boom Last Inspected:	12/23				
Expiry Date of last Commercial Vehicle Inspection:	12/23				

Tool Box	X YES <input type="checkbox"/> NO	Tip Hose	X YES <input type="checkbox"/> NO	Outrigger Pads	X YES <input type="checkbox"/> NO
Spare Remote	X YES <input type="checkbox"/> NO	Water Hose	X YES <input type="checkbox"/> NO		

*Reman engine installed by Mack in 2016 @ 382,026 miles and 13,493 engine hrs
 Refurbished pump by CPR in 2017 which includes all new hydraulic pumps and converted from a 58 to a 61 meter

DATE OF EVALUATION:	7/8/24
COMPLETED BY:	Jason Pitt


FOR QUESTIONS OR ASSISTANCE, PLEASE CONTACT JASON PITT:

jasonpitt@pumppartners.com | 615-476-7606



**concrete
PUMP PARTNERS**
YOUR PARTNER IN CONCRETE PLACEMENT





**concrete
PUMP PARTNERS**
YOUR PARTNER IN CONCRETE PLACEMENT

