

USED EQUIPMENT CHECKLIST

CONTACT DETAILS

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE:	Nashville, TN
PHONE:	615-476-7606	POSTAL CODE/ZIP:	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY:	US
ASKING PRICE: (INCL. COMMISSIONS)		BOTTOM LINE: (INCL. COMMISSIONS)	

TRUCK SPECIFICATIONS

YEAR:	2006	MAKE:	Mack	MODEL:	MR688S
VIN	1M2L197C67M030032	ENGINE MAKE:	Mack	MILEAGE:	1045194
TRANSMISSION SPEEDS:	9	ENGINE HRS:	36371	ENGINE HP:	
TRANSMISSION TYPE:	Mack			DOES A/C FUNCTION	yes

TRUCK: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
Engine rebuilt by Mack	Jan. 14, 2025	\$30,286.49

YEAR:	2006	BRAND:	Schwing	MODEL:	KVM 39XD
SERIAL #:	1705220510	BOOM LENGTH:	39XD	PUMP KIT:	2023-5
FOLD STYLE:	XROLL <input type="checkbox"/> BOOM	RADIO REMOTE:	XYES <input type="checkbox"/> NO	PUMP HOURS:	1673
PROPORTIONAL:	XYES <input type="checkbox"/> NO	CYLINDER SIZE:	9"		

PUMP: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
Updated computer system on pump CPC 3	June 2022	

COMPLETE EVALUATION

--

		Excellent	Very Good	Good	Fair
General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Overall Condition - Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Operations – Truck	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Condition - Truck	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Exterior Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Interior Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Front Tires:	80%				
Rear Tires:	80%				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
PTO Value:	Enter % here.				
Wear Part Value:	75%				
Material Cylinders:	75%				
Boom System:	50%				
Agitator:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Hopper Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Paint Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Boom Certified:	X YES <input type="checkbox"/> NO				
Date Boom Last Inspected:	Aug. 2024				
Expiry Date of last Commercial Vehicle Inspection:	Sept. 2025				


INCLUDED WITH UNIT					
Tool Box	<input type="checkbox"/> YES X NO	Tip Hose	X YES <input type="checkbox"/> NO	Outrigger Pads	X YES <input type="checkbox"/> NO
Spare Remote	<input type="checkbox"/> YES X NO	Water Hose	X YES <input type="checkbox"/> NO		

DATE OF EVALUATION:	February 20, 2025
COMPLETED BY:	Eric Ball


For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606