

USED EQUIPMENT CHECKLIST

CONTACT DETAILS

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE:	Nashville, TN
PHONE:	615-476-7606	POSTAL CODE/ZIP:	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY:	US

TRUCK SPECIFICATIONS

YEAR:	2015	MAKE:	Mack	MODEL:	Mack
VIN	1M2AV04C6FM013312	ENGINE MAKE:	Mack	MILEAGE:	450
TRANSMISSION SPEEDS:	9 speed	ENGINE HRS:	22079h 42m	ENGINE HP:	176,841
TRANSMISSION TYPE:	Eaton Fuller RT016908LL			DOES A/C FUNCTION:	Yes

TRUCK: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
Replaced turbo	4/23	
New brakes and drums	4/25	
New trunnions, both axles	4/25	

PUMP SPECIFICATIONS

YEAR:	2015	BRAND:	Alliance	MODEL:	JXR 38-4.16
SERIAL #:	159	BOOM LENGTH:	38 meter	PUMP KIT:	16 cell
FOLD STYLE:	X ROLL <input type="checkbox"/> Z BOOM	RADIO REMOTE:	X YES <input type="checkbox"/> NO	PUMP HOURS:	3390
PROPORTIONAL:	X YES <input type="checkbox"/> NO	CYLINDER SIZE:	9 inch		

PUMP: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
New Scanreco receiver	12/23	
New dump valve coil	7/25	
New grease distribution block	7/25	
New turret horsehead and bushings	11/25	

COMPLETE EVALUATION

		Excellent	Very Good	Good	Fair
--	--	-----------	-----------	------	------

General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Overall Condition - Pump	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Operations – Truck	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Condition - Truck	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Exterior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Interior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Front Tires:	30% wear				
Rear Tires:	40% wear				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
PTO Value:	N/A				
Wear Part Value:	50% wear				
Material Cylinders:	50% wear				
Boom System:	55% wear				
Agitator:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Hopper Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Paint Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Boom Certified:	X YES <input type="checkbox"/> NO				
Date Boom Last Inspected:	11/25				
Expiry Date of last Commercial Vehicle Inspection:	2/26				

INCLUDED WITH UNIT

Tool Box	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Tip Hose	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Outrigger Pads	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Spare Remote	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Water Hose	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		

Replaced 2nd section hydraulic cylinder seals – 2/25

DATE OF EVALUATION:	12/1/25
COMPLETED BY:	J. Pitt

For questions or assistance, please contact Jason Pitt:

jasonpitt@pumppartners.com | 615-476-7606




For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606




For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
 jasonpitt@pumppartners.com | 615-476-7606