

USED EQUIPMENT CHECKLIST

CONTACT DETAILS

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE,	Nashville, TN
PHONE:	615-476-7606	POSTAL CODE/ZIP	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY	US

TRUCK SPECIFICATIONS

YEAR:	2019	MAKE:	Mack	MODEL:	Granite
VIN	1M2GR4GC9KM003241	ENGINE MAKE:	Mack MP8	MILEAGE:	50,986 mi
TRANSMISSION SPEEDS:	6 speed	ENGINE HRS:	6425h 45m	ENGINE HP:	505
TRANSMISSION TYPE:	Allison automatic			DOES A/C FUNCTION	Yes

TRUCK: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
Replaced 7 th injector	9/25	
New rear differential and power divider	12/24	
New clutch	12/24	

PUMP SPECIFICATIONS

YEAR:	2020	BRAND:	Everdigm	MODEL:	ECP38ZX
SERIAL #:	1131	BOOM LENGTH:	38 meter	PUMP KIT:	16 cell
FOLD STYLE:	<input type="checkbox"/> ROLL <input checked="" type="checkbox"/> Z BOOM	RADIO REMOTE:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	PUMP HOURS:	851.4
PROPORTIONAL:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CYLINDER SIZE:	9in		

PUMP: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
New proximity sensors	11/25	
New agitator motor	2/25	

COMPLETE EVALUATION

		Excellent	Very Good	Good	Fair
General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Overall Condition - Pump	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Operations – Truck	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Condition - Truck	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Exterior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Interior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Front Tires:	30% wear				
Rear Tires:	30% wear				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
PTO Value:	N/A				
Wear Part Value:	50% wear				
Material Cylinders:	30% wear				
Boom System:	30% wear				
Agitator:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Hopper Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Paint Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Boom Certified:	X YES <input type="checkbox"/> NO				
Date Boom Last Inspected:	April 2025				
Expiry Date of last Commercial Vehicle Inspection:	January 2026				

INCLUDED WITH UNIT					
Tool Box	<input type="checkbox"/> YES X NO	Tip Hose	X YES <input type="checkbox"/> NO	Outrigger Pads	X YES <input type="checkbox"/> NO
Spare Remote	<input type="checkbox"/> YES <input type="checkbox"/> NO	Water Hose	X YES <input type="checkbox"/> NO		

--	--	--	--	--	--

DATE OF EVALUATION:	11/20/2025
COMPLETED BY:	C. Mims

For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606





For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606