

## USED EQUIPMENT CHECKLIST

### CONTACT DETAILS

|                        |                            |                          |               |
|------------------------|----------------------------|--------------------------|---------------|
| <b>COMPANY NAME:</b>   | Concrete Pump Partners     | <b>CONTACT NAME:</b>     | Jason Pitt    |
| <b>STREET ADDRESS:</b> | 3950 Dickerson Pike        | <b>CITY, PROV/STATE,</b> | Nashville, TN |
| <b>PHONE:</b>          | 615-476-7606               | <b>POSTAL CODE/ZIP</b>   | 37207         |
| <b>EMAIL:</b>          | jasonpitt@pumppartners.com | <b>COUNTRY</b>           | US            |

### TRUCK SPECIFICATIONS

|                             |                   |                     |           |                          |            |
|-----------------------------|-------------------|---------------------|-----------|--------------------------|------------|
| <b>YEAR:</b>                | 2018              | <b>MAKE:</b>        | Mack      | <b>MODEL:</b>            | Terrapro   |
| <b>VIN</b>                  | 1M2AV09C0JM017728 | <b>ENGINE MAKE:</b> | Mack MP8  | <b>MILEAGE:</b>          | 121,408 mi |
| <b>TRANSMISSION SPEEDS:</b> | 18 speed          | <b>ENGINE HRS:</b>  | 13844h 3m | <b>ENGINE HP:</b>        | 505        |
| <b>TRANSMISSION TYPE:</b>   | Maxitorque manual |                     |           | <b>DOES A/C FUNCTION</b> | Yes        |

### TRUCK: Change/Overhaul/Rebuild

|                         |              |                 |
|-------------------------|--------------|-----------------|
| <b>LIST:</b>            | <b>DATE:</b> | <b>COMMENT:</b> |
| Transmission and clutch | 1/25         |                 |
| New rear differential   | 11/24        |                 |
|                         |              |                 |
|                         |              |                 |

### PUMP SPECIFICATIONS

|                      |                                                                             |                       |                                                                        |                    |            |
|----------------------|-----------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------|--------------------|------------|
| <b>YEAR:</b>         | 2017                                                                        | <b>BRAND:</b>         | Everdigm                                                               | <b>MODEL:</b>      | ECP5616CXL |
| <b>SERIAL #:</b>     | 1026                                                                        | <b>BOOM LENGTH:</b>   | 56 meter                                                               | <b>PUMP KIT:</b>   | 16 cell    |
| <b>FOLD STYLE:</b>   | <input type="checkbox"/> ROLL<br><input checked="" type="checkbox"/> Z BOOM | <b>RADIO REMOTE:</b>  | <input checked="" type="checkbox"/> YES<br><input type="checkbox"/> NO | <b>PUMP HOURS:</b> | 3804       |
| <b>PROPORTIONAL:</b> | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO         | <b>CYLINDER SIZE:</b> | 9 in                                                                   |                    |            |

### PUMP: Change/Overhaul/Rebuild

|                        |              |                 |
|------------------------|--------------|-----------------|
| <b>LIST:</b>           | <b>DATE:</b> | <b>COMMENT:</b> |
| New material cylinders | 9/24         |                 |
| New mud cups           | 10/25        |                 |
| New accumulator pump   | 3/25         |                 |

### COMPLETE EVALUATION

|                                 |                                    |                          |                                     |                          |                          |
|---------------------------------|------------------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|
|                                 |                                    | Excellent                | Very Good                           | Good                     | Fair                     |
| General <b>Operation</b> – Pump | Check box <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

|                                                    |                                    |                          |                          |                          |                          |
|----------------------------------------------------|------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|
| Overall <b>Condition</b> - Pump                    | Check box                          | <input type="checkbox"/> | X                        | <input type="checkbox"/> | <input type="checkbox"/> |
| General Operations – Truck                         | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| General Condition - Truck                          | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Cab Exterior Condition:                            | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Cab Interior Condition:                            | Check box                          | <input type="checkbox"/> | X                        | <input type="checkbox"/> | <input type="checkbox"/> |
| Front Tires:                                       | 10% wear                           |                          |                          |                          |                          |
| Rear Tires:                                        | 30% wear                           |                          |                          |                          |                          |
| PTO Condition:                                     | Check box <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| PTO Value:                                         | N/A                                |                          |                          |                          |                          |
| Wear Part Value:                                   | 40% wear                           |                          |                          |                          |                          |
| Material Cylinders:                                | 10%                                |                          |                          |                          |                          |
| Boom System:                                       | 5% wear                            |                          |                          |                          |                          |
| Agitator:                                          | Check box                          | <input type="checkbox"/> | X                        | <input type="checkbox"/> | <input type="checkbox"/> |
| Hopper Condition:                                  | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Paint Condition:                                   | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Boom Certified:                                    | X YES <input type="checkbox"/> NO  |                          |                          |                          |                          |
| Date Boom Last Inspected:                          | 9/25                               |                          |                          |                          |                          |
| Expiry Date of last Commercial Vehicle Inspection: | 1/26                               |                          |                          |                          |                          |

| INCLUDED WITH UNIT |                                                          |            |                                   |                |                                   |
|--------------------|----------------------------------------------------------|------------|-----------------------------------|----------------|-----------------------------------|
|                    |                                                          |            |                                   |                |                                   |
| Tool Box           | <input type="checkbox"/> YES X NO                        | Tip Hose   | X YES <input type="checkbox"/> NO | Outrigger Pads | X YES <input type="checkbox"/> NO |
| Spare Remote       | <input type="checkbox"/> YES <input type="checkbox"/> NO | Water Hose | X YES <input type="checkbox"/> NO |                |                                   |

|  |
|--|
|  |
|--|

|                            |  |
|----------------------------|--|
| <b>DATE OF EVALUATION:</b> |  |
| <b>COMPLETED BY:</b>       |  |

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606



---

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606





---

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606





---

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606





---

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606

