

## USED EQUIPMENT CHECKLIST

### CONTACT DETAILS

|                        |                            |                          |               |
|------------------------|----------------------------|--------------------------|---------------|
| <b>COMPANY NAME:</b>   | Concrete Pump Partners     | <b>CONTACT NAME:</b>     | Jason Pitt    |
| <b>STREET ADDRESS:</b> | 3950 Dickerson Pike        | <b>CITY, PROV/STATE,</b> | Nashville, TN |
| <b>PHONE:</b>          | 615-476-7606               | <b>POSTAL CODE/ZIP</b>   | 37207         |
| <b>EMAIL:</b>          | jasonpitt@pumppartners.com | <b>COUNTRY</b>           | US            |

### TRUCK SPECIFICATIONS

|                             |                   |                     |        |                          |         |
|-----------------------------|-------------------|---------------------|--------|--------------------------|---------|
| <b>YEAR:</b>                | 2015              | <b>MAKE:</b>        | Mack   | <b>MODEL:</b>            | MRU613  |
| <b>VIN</b>                  | 1M2AX20C9GM001295 | <b>ENGINE MAKE:</b> | Mack   | <b>MILEAGE:</b>          | 128,585 |
| <b>TRANSMISSION SPEEDS:</b> | 6 speed           | <b>ENGINE HRS:</b>  | 14,464 | <b>ENGINE HP:</b>        | 450     |
| <b>TRANSMISSION TYPE:</b>   | Allision Auto     |                     |        | <b>DOES A/C FUNCTION</b> | Yes     |

### TRUCK: Change/Overhaul/Rebuild

| LIST:                      | DATE:         | COMMENT: |
|----------------------------|---------------|----------|
| New transmission           | November 2025 |          |
| New radiator               | December 2022 |          |
| New DPF filter             | April 2024    |          |
| New fuel injector and cups | April 2024    |          |

### PUMP SPECIFICATIONS

|                      |                                                                             |                       |                                                                        |                    |             |
|----------------------|-----------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------|--------------------|-------------|
| <b>YEAR:</b>         | 2015                                                                        | <b>BRAND:</b>         | Putzmeister                                                            | <b>MODEL:</b>      | BSF 47.Z16H |
| <b>SERIAL #:</b>     | 210604455                                                                   | <b>BOOM LENGTH:</b>   | 47 meter                                                               | <b>PUMP KIT:</b>   | 16 cell     |
| <b>FOLD STYLE:</b>   | <input type="checkbox"/> ROLL<br><input checked="" type="checkbox"/> Z BOOM | <b>RADIO REMOTE:</b>  | <input checked="" type="checkbox"/> YES<br><input type="checkbox"/> NO | <b>PUMP HOURS:</b> | 3245.47     |
| <b>PROPORTIONAL:</b> | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO         | <b>CYLINDER SIZE:</b> | 9 in                                                                   |                    |             |

### PUMP: Change/Overhaul/Rebuild

| LIST:                                                                         | DATE:         | COMMENT: |
|-------------------------------------------------------------------------------|---------------|----------|
| New PTO gear box                                                              | May 2025      |          |
| New material cylinders, transitions, muds cups, spectacle plate, cutting ring | June 2025     |          |
| New front and rear s-tube bearings                                            | November 2025 |          |
| Rebuilt LF outrigger cylinder                                                 | March 2025    |          |
| New deck pipe                                                                 | June 2025     |          |

| COMPLETE EVALUATION                                |                                    |                          |                          |                          |                          |
|----------------------------------------------------|------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|
|                                                    |                                    | Excellent                | Very Good                | Good                     | Fair                     |
| General <b>Operation</b> – Pump                    | Check box <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Overall <b>Condition</b> - Pump                    | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | X                        |
| General Operations – Truck                         | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| General Condition - Truck                          | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Cab Exterior Condition:                            | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | X                        |
| Cab Interior Condition:                            | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | X                        |
| Front Tires:                                       | 30% wear                           |                          |                          |                          |                          |
| Rear Tires:                                        | 30% wear                           |                          |                          |                          |                          |
| PTO Condition:                                     | Check box <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> | <input type="checkbox"/> |
| PTO Value:                                         | 10% wear                           |                          |                          |                          |                          |
| Wear Part Value:                                   | 10% wear                           |                          |                          |                          |                          |
| Material Cylinders:                                | 10% wear                           |                          |                          |                          |                          |
| Boom System:                                       | 50% wear                           |                          |                          |                          |                          |
| Agitator:                                          | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Hopper Condition:                                  | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | X                        | <input type="checkbox"/> |
| Paint Condition:                                   | Check box                          | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | X                        |
| Boom Certified:                                    | X YES <input type="checkbox"/> NO  |                          |                          |                          |                          |
| Date Boom Last Inspected:                          | October 2025                       |                          |                          |                          |                          |
| Expiry Date of last Commercial Vehicle Inspection: | March 2026                         |                          |                          |                          |                          |

| INCLUDED WITH UNIT |                                                                     |            |                                                                     |                |                                                                     |
|--------------------|---------------------------------------------------------------------|------------|---------------------------------------------------------------------|----------------|---------------------------------------------------------------------|
| Tool Box           | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | Tip Hose   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | Outrigger Pads | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| Spare Remote       | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | Water Hose | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |                |                                                                     |

|                            |              |
|----------------------------|--------------|
| <b>DATE OF EVALUATION:</b> | 11/19/25     |
| <b>COMPLETED BY:</b>       | C. DeMasters |

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606



---

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606



---

For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606



For questions or assistance, please contact Jason Pitt:  
[jasonpitt@pumppartners.com](mailto:jasonpitt@pumppartners.com) | 615-476-7606

