

USED EQUIPMENT CHECKLIST

CONTACT DETAILS

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE,	Nashville, TN
PHONE:	615-476-7606	POSTAL CODE/ZIP	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY	US

TRUCK SPECIFICATIONS

YEAR:	2016	MAKE:	Mack	MODEL:	MRU613
VIN	1M2AV09C5GM015661	ENGINE MAKE:	Mack	MILEAGE:	80,388 m
TRANSMISSION SPEEDS:	18	ENGINE HRS:	11665h	ENGINE HP:	505
TRANSMISSION TYPE:	Maxitorque manual			DOES A/C FUNCTION	Yes

TRUCK: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
New rear steer axle rebuild	September 2025	

PUMP SPECIFICATIONS

YEAR:	2016	BRAND:	Putzmeister	MODEL:	BSF63.18HLS
SERIAL #:	210604454	BOOM LENGTH:	61 meter	PUMP KIT:	18 cell
FOLD STYLE:	<input type="checkbox"/> ROLL <input checked="" type="checkbox"/> Z BOOM	RADIO REMOTE:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	PUMP HOURS:	2614.16h
PROPORTIONAL:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CYLINDER SIZE:	10 in		

PUMP: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
New boom pipe	July 2025	
New S-tube, cutting ring, front and rear bearing housing, agitator paddles	February 2024	
New hopper grate	August 2024	

COMPLETE EVALUATION

		Excellent	Very Good	Good	Fair
--	--	-----------	-----------	------	------

General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
Overall Condition - Pump	Check box	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
General Operations – Truck	Check box	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
General Condition - Truck	Check box	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
Cab Exterior Condition:	Check box	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
Cab Interior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Front Tires:	50% wear				
Rear Tires:	40% wear				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
PTO Value:	N/A				
Wear Part Value:	30% wear				
Material Cylinders:	60% wear				
Boom System:	10% wear				
Agitator:	Check box	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hopper Condition:	Check box	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
Paint Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Boom Certified:	X YES <input type="checkbox"/> NO				
Date Boom Last Inspected:	N/A				
Expiry Date of last Commercial Vehicle Inspection:	12/25				

INCLUDED WITH UNIT					
Tool Box	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Tip Hose	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Outrigger Pads	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Spare Remote	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Water Hose	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		

--


DATE OF EVALUATION:	J.Pitt
COMPLETED BY:	11/17/25

For questions or assistance, please contact Jason Pitt:

jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606




For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606