

USED EQUIPMENT CHECKLIST

CONTACT DETAILS

COMPANY NAME:	Concrete Pump Partners	CONTACT NAME:	Jason Pitt
STREET ADDRESS:	3950 Dickerson Pike	CITY, PROV/STATE,	Nashville, TN
PHONE:	615-476-7606	POSTAL CODE/ZIP	37207
EMAIL:	jasonpitt@pumppartners.com	COUNTRY	US

TRUCK SPECIFICATIONS

YEAR:	2014	MAKE:	Mack	MODEL:	MRU613
VIN	1M2AV04C9EM010984	ENGINE MAKE:	Mack	MILEAGE:	183,317
TRANSMISSION SPEEDS:	9 speed	ENGINE HRS:	19368h	ENGINE HP:	370
TRANSMISSION TYPE:	Maxitorque Manual			DOES A/C FUNCTION	Yes

TRUCK: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
Complete brake job, wheel bearing and seals	12/25	
Load pads and torque rods for rear axles	12/25	
New truck batteries	10/25	
Replaced fan clutch	7/25	

PUMP SPECIFICATIONS

YEAR:	2014	BRAND:	Putzmeister	MODEL:	36-4.16H
SERIAL #:	210603721	BOOM LENGTH:	36 meter	PUMP KIT:	16 cell
FOLD STYLE:	<input type="checkbox"/> ROLL <input checked="" type="checkbox"/> Z BOOM	RADIO REMOTE:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	PUMP HOURS:	
PROPORTIONAL:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CYLINDER SIZE:	9 in		

PUMP: Change/Overhaul/Rebuild

LIST:	DATE:	COMMENT:
New wear plate, cutting rind and pressure spring	1/26	
New hopper grate and vibrator	2/25	
New S tube	7/24	

COMPLETE EVALUATION					
		Excellent	Very Good	Good	Fair
General Operation – Pump	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Overall Condition - Pump	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Operations – Truck	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
General Condition - Truck	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Cab Exterior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X
Cab Interior Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X
Front Tires:	30% wear				
Rear Tires:	30% wear				
PTO Condition:	Check box <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
PTO Value:	N/A				
Wear Part Value:	0% wear				
Material Cylinders:	50% wear				
Boom System:	40% wear				
Agitator:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Hopper Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>
Paint Condition:	Check box	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	X
Boom Certified:	X YES <input type="checkbox"/> NO				
Date Boom Last Inspected:	10/25				
Expiry Date of last Commercial Vehicle Inspection:	4/26				

INCLUDED WITH UNIT					
Tool Box	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Tip Hose	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Outrigger Pads	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Spare Remote	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Water Hose	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		

4/24 – new engine wiring harness, EGR valve, air compressor, water pump, oil cooler
 2/24 – New Reman engine

DATE OF EVALUATION:	1/14/26
COMPLETED BY:	J.Pitt

For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606

TO WRITE ON THIS LABEL USE AN INDELIBLE, PERMANENT INK MARKER, PEN OR PENCIL THAT WILL NOT FADE IN DIRECT SUNLIGHT

ANNUAL VEHICLE INSPECTION LABEL NO. 69633202

COMPLETED: MONTH 04 YEAR 2025

A RECORD OF THIS VEHICLE'S ANNUAL VEHICLE INSPECTION REPORT IS MAINTAINED AT: MOTOR CARRIER OTHER ENTITY

Concrete Pump Partners
COMPANY / NAME

4140 Bishop Ln
STREET

Louisville, Ky, 40288
CITY, STATE, ZIP CODE

502-966-6066 1528195
TELEPHONE MOTOR CARRIER IDENTIFICATION NUMBER

CERTIFICATION: THIS VEHICLE HAS PASSED AN INSPECTION IN ACCORDANCE WITH 49CFR 396.17 THROUGH 396.23.

VEHICLE IDENTIFICATION: IF THE VEHICLE IS NOT READILY, CLEARLY, AND PERMANENTLY MARKED, CHECK ONE AND COMPLETE.

FLEET UNIT NUMBER LICENSE / REGISTRATION NUMBER

VEHICLE IDENTIFICATION NUMBER OTHER 1M2AV04C9EM020984

Copyright 2017 J. J. Keller & Associates, Inc. • Neenah, WI • JJKeller.com • (800) 327-6868 • Printed in the USA 1279 (Rev. 8/17)



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606



For questions or assistance, please contact Jason Pitt:
jasonpitt@pumppartners.com | 615-476-7606

